





BlueGene/L System Package


Update for BG/L Tahoe Conference 8/13/2002 Paul Coteus IBM **Building Blue Gene/L**




BG/L Dual Compute Card



BG/L Dual IO Card




BG/L 32-way node card



BG/L Link Card


- Redrives 1.4Gb/s serial torus & tree links between midplanes
- Redirects links to skip over failed midplanes
- Creates electrically isolated independent machine subpartitions


BG/L Link Card




BG/L Midplane


- 8 x 8 x 8 torus / tree subpartiton
- ~9 KW max inc fans
- 4 dual Gigabit Enet I/O cards
- 16 compute cards
- 4 link cards
- Service card (clock, control, persistent power)
- Distributes 48V DC, fan power, service port
















Equilibrium Temperatures on Card 29 vs. Door Configuration


Air-Inlet Temperature = 27 °C (7 °C hotter than in real machine) Fans Voltage = 48 VDC (full voltage)




BG/L Rack - Covers Off - Concept




BG/L Racks with X-Y-Z Torus Cables



Racks with Covers - Concept





BG/L Reliability & Serviceability

- Individually & globally addressable JTAG network to all ASICs through chainable Gb Ethernet service port.
- ECC or parity / retry with sparing on most busses.
- Uncorrectable errors cause restart from checkpoint.
- Most hardware fails not covered by redundancy or sparing are repaired by switching to "hot" spare racks.
- Only fails early in global clock tree, or certain failures of link cards, require immediate service.

BG/L Reliability Estimates

Component	FIT per component*	Components per 64k partition	FITs per system	Failure rate per week
ETH complex	160	2704	433k	
DRAM	5	599,040	2,995k	
Compute + I/O ASIC	20	66,560	1,331k	
Link ASIC	10	3072	60k	
Clock chip	6.5	~1200	8k	
Non-redundant power supply	500	384	384k	
Total (65,536 compute nodes)			5211k	0.87

•After burn-in and applied redundancy.

T=60C, V=Nom, 40K POH.

FIT = Failures in parts per million per thousand power-on hours.

1 FIT = $0.168*10^{-6}$ fails/week if the machine runs 24 hrs/day.